



February 4, 2010

MR. JAY JOSEPH SENIOR MANAGER PRODUCT REGULATORY OFFICE AMERICAN HONDA MOTOR CO. 1919 TORRANCE BLVD. TORRANCE, CA 90501-2746

NVS-215dgl 10V-033

SUBJECT: POWER WINDOW SWITCH

DEAR MR. JOSEPH:

This letter serves to acknowledge American Honda Motor Co.'s (Honda) notification to the National Highway Traffic Safety Administration (NHTSA) of a defect in the vehicles listed below for which a safety recall campaign will be conducted pursuant to Federal law.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HONDA/FIT/2007-2008

NHTSA Campaign Number: 10V-033

Mfg's Report Date: January 27, 2009

Components: VISIBILITY: POWER WINDOW DEVICES AND CONTROLS

Potential Number of Units Affected: 141,000

Summary:

HONDA IS RECALLING CERTAIN MODEL YEAR 2007-2008 FIT VEHICLES. UNDER SEVERE CONDITION, WATER MAY ENTER THE DRIVER'S WINDOW AND REACH THE MASTER POWER WINDOW SWITCH. IF THE MASTER POWER WINDOW SWITCH IS DAMAGED AS A RESULT OF THE WATER INTRUSION, OVERHEATING AND FAILURE OF THE SWITCH MAY RESULT.

Consequence:

AN OVERHEATING SWITCH CAN CAUSE SMOKE, MELTING AND FIRE.

Remedy:

DEALERS WILL INSPECT THE SWITCH AND INSTALL A COVER AROUND THE SWITCH HOUSING TO PREVENT WATER FROM ENTERING THE SWITCH. IF THE SWITCH IS DAMAGED, THE SWITCH WILL BE REPLACED AND A COVER WILL BE INSTALLED. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS MAY CONTACT HONDA AT 1-800-999-1009.

Notes:

CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO HTTP://WWW.SAFERCAR.GOV.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Please provide the following additional information and be reminded of the following requirements:

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available.

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within 30 days after the close of the calendar quarter in which the campaign was initiated. Thereafter, quarterly reports will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Delia Lopez who may be reached by phone at 202-366-9525, or by email at Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you toward a successful completion of this recall campaign.

Sincerely,

George H. Person

Chief, Recall Management Division Office of Defects Investigation

Enforcement